


SUN COI FABRICS



Openness 1 & 3 & 5 %





FOCUS ON QUALITY

Cutting: Cold Cut, Ultrasonic, Crush Cut, or Laser Seaming / Hemming: Thermal, High–Frequency, Ultrasonic, or Sewing

OMEGA

SC-A2-01 (1% & 3% & 5%)	Sc-ac-al (1% & 3% & 5%)	SC-A2-O3 (1% & 3% & 5%)
KonstantKo	And	Sc-a2-og (1%&3%&5%)
Sc-ac-b (1%&3%&5%)	SC-22-1 (1% & 3% & 5%)	

TECHNICAL PARAMETER

COMPOSITION	30%Polyester + 70%	PVC
FINISHED WIDTH	98/118 inch	
THICKNESS	0.030" ± 5%	
WEIGHT	13.84 oz/yd ² ± 5 %	
COLOR FASTNESS	8 Grade	
YARN COUNT	64 * 40	
BREAKING STRENGTH	Warp 2060 N/5cm	Weft 1300 N
COMPOSITION	30%Polyester + 70%	PVC
FINISHED WIDTH	98/118 inch	
THICKNESS	0.026" ± 5%	
WEIGHT	12.96 oz/yd ² ± 5 %	
COLOR FASTNESS	8 Grade	
YARN COUNT	54 * 44	
BREAKING STRENGTH	Warp 1800 N/5cm	Weft 1434 N
COMPOSITION	30%Polyester + 70%	PVC
FINISHED WIDTH	98/118 inch	
THICKNESS	0.022" ± 5%	
WEIGHT	12.08 oz/yd ² ± 5 %	
COLOR FASTNESS	8 Grade	
YARN COUNT	48 * 46	

PRODUCT CERTIFICATION

HEALTH CERTIFICATION	GREENGUARD GOLD、REACH、CHINA GB/T 2912.1-2009、SGS
BACTERIA AND FUNGAL RESISTANCE	ASTM G21 GB/T 31402-2015/ISO 22196:2007(IDT)
FIRE RESISTANCE	B1 (CHINA)、NFPA701 (USA)
COLOR FASTNESS	8 Grade
WARRANTY	5-years
FABRICATION METHODS	Cutting: cold cut / ultrasonic / crush cut Seaming / Hemming: thermal / high-freque
CARE AND CLEANING	Remove dust with vacuum cleaner or comp Do not use solvents or any abrasive substa Rinse with clean water. Leave the shade do You can also rub the fabric very gently with



1%

) N/5cm

3%

N/5cm

5%

BREAKING STRENGTH Warp 1600 N/5cm Weft 1500 N/5cm

INA ENVIRONMENTAL LABELLING

equency / ultrasonic / sewing

compressed air.

ubstance which might damage the coating of the fabric.

ade down until completely dry.

with a clean white pencil eraser to remove small stains.







